

Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Chenango Bridge Elementary School

Phase 1

Asphalt Pavement Reconstruction

Reconstruct asphalt parking located on west side of building including access drive.

Sidewalk Replacement

Replace cracked sections of concrete sidewalk.

Repoint Mortar

Repoint brick mortar joints at select areas and clean brick surface.

Lintel Repair

Remove surface rust and paint exterior lintels.

Roof Replacement

Replace small roof near loading dock with single ply roof membrane system.

Porcelain Panel Replacement

Provide new exterior panel above windows at rear of building.

Window Replacement

Replace windows throughout building.

Phase 2

Structural Floor Repair

Remove surface rust on metal deck in basement and paint to prevent further corrosion.

Hollow Metal Door Replacement

Replace deteriorated hollow metal doors with FRP doors in aluminum frames.

Corridor Terrazzo Refinishing

Grind down terrazzo flooring in corridors.

Quarry Tile Replacement

Replace cracked quarry tile in specific locations.

Gymnasium Equipment Replacement

Replace gym scoreboards, wall padding and basketball backstop assemblies.

Arc Flash Study

Provide arc flash study and label all panelboards and required equipment. Clean main electrical gear.

Classroom LED Lighting

Upgrade classrooms to LED lighting with dimming control, daylight harvesting, and occupancy control.



Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Chenango	Bridge	Elementary	School
----------	--------	------------	--------

Classroom Power Pole Removal

Remove power poles in existing classrooms.

Multi-Purpose Room Technology Upgrades

Provide new sound system and projector in multi-purpose room.

Hot Water Distribution Piping Improvements

Reconfigure pipe recirculating loop to get hot water to all parts of the building.

Hose Bibb Replacement

Replace hose bibbs due to age of equipment.

Mixing Valve Replacement

Replace mixing valve due to age. Provide unit with low flow capacity.

Backflow Preventer

Add backflow preventer to boiler.

Makeup Water Meter

Add makeup water meter to boiler.

Water Bottle Filler

Replace one drinking fountains with water bottle filler.

Boiler Room Ventilation

Add boiler room ventilation.

Heat Pump Replacement

Replace obsolete heat pumps due to age.

Gas Piping Support Replacement

At rooftop units, replace natural gas piping supports on the roof.

Crawl Space Ventilation

Provided tempered mechanical ventilation in the crawlspace to help reduce the amount of moisture.

Exit Discharge Lighting

Add emergency exterior fixtures at exits.

Accessible Signage

Provide accessible signage.

Cabinetry Replacement

Consider replacement of all plastic laminate cabinetry with new laminate cabinets and solid surfacing counters.

Nurses Office Expansion

Renovate existing space to create an expanded nurses office area

Add Faculty Toilet Rooms

Add faculty toilet rooms by renovating existing space.

11/7/2017 2



Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

Chenango Bridge Elementary School
Corridor Finish Improvements
Improve appearance of corridors by upgrading finishes.
Splitting Up of Classroom
Create flexible classroom space by adding folding partitions to
existing classroom.
Updating of Finishes
Improve appearance of classrooms by upgrading finishes.
OT/PT Improvements
Create more functional OT/PT space.
Classroom Furniture Replacement
Replace classroom furniture
STEAM Classroom
Renovate an existing classroom into a STEAM room.

FACILITY TOTAL \$3,473,000



Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

Port Dickinson Elementary School

Phase 1

Bus Drive Pavement Reconstruction

Replace bus loop pavement.

Curb Replacement

Replace bus loop concrete curb.

Concrete Sidewalk Replacement

Replace bus loop concrete walk.

Play Area Pavement Replacement

Replace pavement at play area.

Fence Replacement

Provide new chain link fence along a majority of the southern property line.

Repoint Mortar

Repoint mortar joints at exterior brick and repair damaged plaster in required areas.

Stone Step Replacement

Replace worn stone steps at front of original building, clean stone and paint upper railing.

Window Replacement

Replace windows with higher quality windows to allow better operation despite window size. Replace window panels and interior shades at same time.

Gutter Refurbishment

Replace sections of wood as needed and paint gutter system.

Wood Trim Replacement

Replace deteriorated wood as needed and paint trim. Investigate condition of copper.

Shingle Roof Replacement

Replace aging asphalt shingles at sloped roof areas of original building.

Phase 2

Hollow Metal Door Replacement

Provide FRP door in aluminum frame at roof and rear door. Provide new hollow metal door and frame matching original design at front door.

Carpet Replacement

Consider replacement of library and main office carpet.

Vinyl Tile Replacement

Replace areas of vinyl tile.



Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Corridor Terrazzo Refinishing

Grind down terrazzo flooring in corridors.

Gymnasium Equipment Replacement

Replace gym scoreboards, wall padding and basketball backstop assemblies.

Water Bottle Filler

Replace one drinking fountains with water bottle filler.

Arc Flash Study

Provide arc flash study and label all panelboards and required equipment. Clean main electrical gear.

Classroom LED Lighting

Upgrade classrooms to LED lighting with dimming control, daylight harvesting, and occupancy control.

Classroom Power Pole Removal

Remove power poles in existing classrooms.

Multi-Purpose Room Technology Upgrades

Provide new sound system and projector in multi-purpose room.

Heat Pump Replacement

Replace half of the heat pumps that are starting to get older.

Circulation Pump Replacement

Replace circulation pumps on heat pump loop due to age.

Cabinet Heater Replacement

Replace cabinet heaters due to age.

Health Office HVAC

Provide ventilation at health office separate from the rest of the building.

Work Room HVAC

Provide HVAC system for second floor work room.

Exit Discharge Lighting

Add emergency exterior fixtures at exits.

Handicap Toilet Room Renovations

Renovate nurses office and three toilet rooms off of classrooms to make accessible.

Accessible Signage

Provide accessible signage.

Toilet Partition Replacement

Replace partitions with solid plastic partitions.

Gym Operable Partition Laminate

Screw gym folding partition laminate to adhere it to substrate.

Toilet Room Renovations

Renovate toilet rooms to make more aesthetic.

11/7/2017 5



Chenango Valley Central School District Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

Port Die	ckinson Elementary School
Handica	ap Changing Area at Nurses Office
	Create handicap changing area at nurses office.
Locker	Room Conversions
	Convert locker rooms to storage rooms.
OT/PT I	mprovements
	Create more functional OT/PT space.
Updatir	ng of Finishes
	Improve appearance of classrooms by upgrading finishes.
Classro	om Furniture Replacement
	Replace classroom furniture including Library.
Replace	e Bus Entrance Doors
	Replace bus entrance doors and frames
Cabinet	try Replacement
	Consider replacement of all plastic laminate cabinetry with new
STEAM	laminate cabinets and solid surfacing counters. Classroom
0.2	Renovate an existing classroom into a STEAM room.
2nd Flo	or Toilet Room
ZIIU FIO	
	Add an individual toilet room on the 2nd floor level.
Y TOTAL	\$4,311,000



Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Middle / High School

Phase 1

Trench Drain Replacement

Replace trench drain at west side parking lot with a concrete structure and replace adjacent asphalt. Other option is to remove drain and associated exit drive.

South Drive Asphalt Reconstruction

Reconstruct existing asphalt at the south drive.

Athletic Field Parking Lot

Pave existing gravel parking lot.

Sidewalk Repair

Provide sealant at locations of large gaps between sections of concrete sidewalk.

Tennis Court Repair

Patch tennis court cracks and apply new acrylic coating.

Softball Field Netting

Provide netting between softball field and parking area.

Gas House Updates

Replace windows and doors and repoint brick at gas house.

Leveling Replacement

Remove loose leveling material in storage room and provide new concrete leveling to match existing thickness.

Repoint Mortar

Repair exterior cracks in brick and repoint mortar in required areas.

Concrete Pad Replacement

Replace concrete pads at Exterior Doors that have deterioration.

MS Gym Floor Replacement

Replace wood floor in Middle School gym.

MS Gym Wall Padding

Provide wall padding in MS gym.

MS Gym Mat Hoist

Provide matt hoist in MS gym for storage of wrestling mats.

Stadium Lights

Provide athletic lights at stadium

Phase 2

Hollow Metal Door Replacement

Replace existing hollow metal doors and frames with FRP doors and aluminum frames.

Vinyl Tile Replacement

Remove cracked vinyl tile and install new tile. Cut in control joints where cracking is occurring at building expansion joints.



Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Ceiling Tile Replacement

Replace ceiling in 2nd floor storage room and stained tiles in specific locations.

Pool Locker Replacement

Replace rusted pool lockers with plastic lockers that will not rust.

Wood Door Replacement

Replace deteriorated wood doors with FRP doors at pool.

Window Replacement

Replace windows in the MS gym and pool to allow more light into the spaces.

Bleacher Fencing

Provide fencing in front of bleachers

Baseball Field Bleachers

Replace existing bleachers with new aluminum bleacher system on concrete pad with panels at front.

Gym Bleacher Replacement

Replace HS gym bleachers.

HS Gym Floor Refinishing

Refinish wood floor in High School gym.

HS Gym Score Board Replacement

Replace scoreboard in HS gym

Bleacher Side Curtains

Provide curtains at bleacher sides to prevent access under bleacher.

HS Gym Wall Padding

Replace HS gym wall padding.

Batting Cage

Provide batting cage for HS gym with automatic operation for raising and lowering.

Handicap Accessible Door Operator

Provide automatic door operator at two entries to improve handicap accessibility.

Arc Flash Study

Provide arc flash study and adhere labelling to equipment.

Classroom LED Lighting

Upgrade classrooms to LED lighting with dimming control, daylight harvesting, and occupancy control.

LED Gym Lighting

Upgrade High School gym to LED High Bay gym lighting with dimming and day lighting controls.

Clock System Replacement

Provide new wireless clock system / bell system.



Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Middle / High School

Pool Timing System Replacement

Replace pool timing system including new scoreboard and touchpads.

Pool Repairs

Replace pool filtration tanks.

Backflow Preventer Installation

Add backflow preventer to boiler system.

Makeup Water Meter Installation

Add makeup water meter to Boiler.

Water Bottle Fillers

Replace two drinking fountains with water bottle fillers.

Cafeteria Serving Line HVAC Improvements

MS & HS cafeteria serving line HVAC Improvements.

Middle School Gym Air Conditioning

Provide air conditioning in the MS gym.

Visual Fire Alarm Devices

Add visible signal devices in all multi-occupant support spaces and all classrooms.

Add Emergency Transfer Switch

Separate the life safety loads into a "life safety" transfer switch with priority over non-essential loads. Refeed emergency lighting panels and circuits from life safety system.

Gender Neutral Locker Area

Create gender neutral changing areas in each locker room.

Create Outdoor Classroom

Create outdoor classroom adjacent to pond.

STEAM Room Renovation

Convert classroom into a room dedicated to STEAM.

Library Renovations

Renovate existing library to create modern technology library and provide professional development space.

Athletic Field Concession and Toilet Rooms

Create addition adjacent to HS gym for toilet rooms and concession stand for multi-purpose field use.

MS Main Office Entry Improvements

Remove lockers and add glass adjacent to entrance door.

CSE Office Waiting Area

Create waiting area at SCE office by removing toilet room.

Gender Neutral Toilet Rooms

Create gender neutral toilet rooms.

Fitness Room Expansion

Expand existing fitness room into existing wrestling room. Cost does not include equipment.



Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

Middle / High School

Sustainable Greenhouse

Provide greenhouse adjacent to the pond with sustainable features.

FACILITY TOTAL \$4,048,000



Potential Capital Project

BCK-IBI Group Project No. 38209

October 23, 2017

Bus	Garage	,
-----	--------	---

Р			

Hollow Metal Door Replacement

Replace older hollow metal doors with FRP doors in aluminum frames.

Overhead Door Replacement

Replace wood overhead doors with steel doors.

Window Replacement

Replace original windows with aluminum frame windows with insulated glass.

Switchgear Replacement

Replace switchgear due to age.

Backflow Preventer Installation

Add a backflow preventer.

Makeup Water Meter Installation

Add a makeup meter.

Office Exhaust Fan Replacement

Replace office exhaust fan due to age.

Parts Storage Exhaust Fan Replacement

Replace parts storage exhaust fan due to age.

New Gas Rooftop System

Provide rooftop unit to eliminate thru wall A/C units.

Insulate Piping

Insulate hot water piping in boiler room.

Fire Alarm System

Add fire alarm system.

Accessible Toilet Rooms

Adjust fixture and locations to make toilet room accessible.

Accessible Door Hardware

Provide accessible door hardware.

Accessible Signage

Provide accessible signage.

Asbestos Vinyl Tile

Although in good condition, consider replacement of asbestos floor tile with vinyl tile.

Bus Storage Area Expansion

Expand existing bus storage area on one side of building.



Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

Bus Garage

Maintenance Bay Lift

Provide a lift in open maintenance bay. Includes raising the roof height up to provide the proposer clearance.

Kitchen Area Upgrades

Replace finishes and cabinets in kitchen area.

FACILITY TOTAL

\$1,025,000



Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

Storage Building (Field House)

Phase 2

Accessible Entrance

Build-up asphalt at team room entrance doors to provide proper accessibility.

Accessible Signage

Provide accessible signage at toilet rooms and team rooms.

FACILITY TOTAL \$4,000



FACILITY TOTAL

Chenango Valley Central School District

Potential Capital Project BCK-IBI Group Project No. 38209

October 23, 2017

	Maintenance Storage Building
Phase 2	
	Metal Panel Replacement
	Provide new exterior metal panels.
	Wood Door Replacement
	Install new FRP door in aluminum frame.
	Roof Replacement
	Provide new metal roof panels.
	Fascia Replacement
<u></u>	Provide new wood blocking and metal fascia.
	Gutter Replacement
	Provide continuous gutter system and tie into future storm system.
	Accessible Door Hardware
	Provide accessible door hardware.

11/7/2017

\$93,000